

# DICOM Viewer Shortcuts

## General Shortcuts

	Go to previous image
	Go to next image
	Go to previous series
	Go to next series
	Activate fast scroll between series
	Open context menu
	Export study
	Print active image
	Help
	Toggle full screen

## Linking and Lines

	Reference lines
	Auto or manual link translation synchronization
	Unlink translation synchronization
	Display Reset

## Measurements

	Select distance measurement tool
	Select angle measurement tool
	Delete all measurements from active viewport
	Delete selected measurement from active viewport

## Rotation

	Select image rotate tool
	Rotate right
	Rotate left
	Flip vertical
	Flip horizontal
	Rotate image with 5 degree steps
	Clear transform

## Cine Tools

	Cine tools
	Stop/Play cine or video or multiframe

## Hanging Protocols

	Apply next hanging protocol
--	-----------------------------

## Zoom and Magnifier

	Select image zooming tool
	Zoom
	Select magnifier tool
	If magnifier tool is active, change magnifier zoom
	If magnifier tool is active, change magnifier dimensions
	Fit image to screen
	Set zoom to 100%
	Set zoom to 200%
	Set zoom to 300%
	Set zoom to 400%
	Increase zoom
	Decrease zoom

## Windowing

	Select image window (brightness/contrast) adjustment tool
	Full dynamic brightness/contrast
	Windowing preset Abdominal CT (wl=60 ww=400)
	Windowing preset Angio CT (wl=300 ww=600)
	Windowing preset Bone CT (wl=300 ww=1500)
	Windowing preset Brain CT (wl=40 ww=80)
	Windowing preset Chest CT (wl=40 ww=400)
	Windowing preset Lungs CT (wl=400 ww=1500)
	Invert
	Show intensity value

## MPR

	Axial reconstruction
	Coronal reconstruction
	Sagittal reconstruction
	Multipanar reconstruction

## Key Objects

	Add instance to the Key Object Selection
	Open the Key Object Selection management dialog

